

### **Splicing & Engineer Accessories**

## **Fiber Optic Cleaner Box**

Dirt, dust, and other contaminants are the enemy of high-speed data transmission over optical fiber. Today's network applications require more bandwidth, making loss budgets tighter than ever. It is critical that all optical connections are clean and free of contaminants to ensure application success.

CLE-BOX is essential accessory to maintain and guarantee good quality of fiber optic connection. It is the best non-alcohol cleaning method for various fiber optic terminations which is simply and swiftly used. Box tape replacement is offered to make sure low cleaning cost .Suitable for connector such as SC 、FC、MU、 LC、ST、D4 、DIN etc.



#### **Standards Compliance**

- IEC 62627: Fiber optic interconnecting devices and passive components Fiber optic connector cleaning methods
- RoHS: Free of hazardous substances according to RoHS 2002/95/EG
- IEC 61300-3-35, which specifies pass/fail requirements for end face quality inspection before connection.

#### **Function**

- Special non-alcohol superfine fiber.
- Well handled and antistatic.
- Friendly using, efficient cleaning.
- Tape made of high density textile fibers. Level of cleaning is 100.
- Cleaning time 500+.
- Easy to replace the tape. •
- **Tape Replacement**



1. Take off sliding cover



2. Take off side cover



3. Take away old tape



4.Put on new tape

# **Ordering Information**



5.Put on side cover



6.Put on sliding cover

Part Number	Dimensions	Description
CLE-BOX-1	115*79*32 mm	Suitable for SC $_{\sim}$ FC $_{\sim}$ MU $_{\sim}$ LC $_{\sim}$ ST $_{\sim}$ D4 $_{\sim}$ DIN connector. (500+ cleans)

